



Zone	Station Point	Linear Feet	Stabilization/Revegetation Recommendation	Ownership Summary
312	S387+85 to 391+40	355	A or G	Stanford
313	S389+55 to 389+95	40	A or B	Stanford
314	S387+00 to 404+24	1724	A	Stanford
315	N392+50 to 393+00	50	A or B	Stanford
316	N393+00 to 397+45	445	A	Stanford
317	N397+45 to 398+60	115	A or (E and B)	Stanford
318	N397+45 to 398+60	115	A or B	Stanford
319	N398+60 to 404+24	564	A	Stanford
320	N400+75 to 401+45	70	A or B	Stanford

Indicates a high priority stabilization project

- Key**
- Existing path/trail at top of bank.
 - Opportunity for new path at top of bank.
 - Opportunity for overlook.
 - Opportunity for small pocket park.
 - Opportunity for interpretive panel site.
 - Add creek identification at road crossing.

- Treatment Alternatives Key**
- A - No Action
 - B - Vegetation Only
 - C - Repair Protection
 - D - Vegetate Structure
 - E - Remove Structure
 - F - Regrade and Replant
 - G - Terrace
 - H - Riprap Toe
 - I - Vegetated Riprap
 - J - Vegetated Wall

See Sheet 17

BANK STABILIZATION AND REVEGETATION RECOMMENDATIONS
 SAN FRANCISCO CREEK
 BANK STABILIZATION & REVEGETATION
 PRELIMINARY MASTER PLAN REPORT